



HARDWARE PHONE SUPPORT

FROM SIERRA EXPERTS

Endpoint Manager Support Phones List

Aastra

Aastra Models: 480i, 91xxi [480i, 480i CT, 9112i, 9133]

- 9112i
- 9133i
- 480i
- 480i CT

Aastra Models: 94xx, 67xx, 9143i [9480i, 9480i CT, 9143i, 67xx]

- 9480i
- 9480i CT
- 9143i
- 6730i
- 6731i
- 6739i
- 6751i
- 6753i
- 6755i
- 6757i
- 6757i CT
- 6735i CT
- 6737i CT

CloudTC

CloudTC Glass Models

- Glass

Thomson

Thomson Model [ST2030S]

- ST2030S

Norphonic

Traphone Model

- Version 8

Digium

Digium Dxx Series: [D40, D50, D70]

- D40
- D50
- D70

Xorcom

Xorcom IP Phones Models: [XP0100, XP0120]

- XP0100
- XP0120

Grandstream

Budgetone series [200, 201]

- BT200
- BT201

GXP Enterprise HD series [2100, 2110, 2120]

- GXP2100
- GXP2110
- GXP2120
- GXP1100
- GXP1105
- GXP1400
- GXP1405

- GXP1450
- GXP2124

GXP Enterprise IP series [280, 1200, 2000, 2010, 2020]

- GXP280
- GXP1200
- GXP2000
- GXP2010
- GXP2020
- GXP285

HandyTone [HT486 REV.2, HT286 REV.3]

- HT486
- HT286

Polycom

Polycom PTX151

- Polycom PTX151
- Polycom PTX150

SoundPoint IP 3xx [320, 330]

- SoundPoint IP 320
- SoundPoint IP 330

SoundPoint IP 430 [430]

- SoundPoint IP 430

We do IT differently.



SoundPoint Old Models [300, 500]

- SoundPoint IP 300
- SoundPoint IP 500

SoundPoint/Station Legacy Models [301, 501, 600, 601, 4000]

- SoundPoint IP 301
- SoundPoint IP 501
- SoundPoint IP 600
- SoundPoint IP 601
- SoundStation IP 4000

SoundPoint/Station/VVX In-Production Models [321, 331, 335, 450, 550, 560, 650, 670, 5000, 6000, 7000, 1500]

- SoundPoint IP 321
- SoundPoint IP 331
- SoundPoint IP 335
- SoundPoint IP 450
- SoundPoint IP 550
- SoundPoint IP 560
- SoundPoint IP 650
- SoundPoint IP 670
- SoundPoint IP 6000
- SoundPoint IP 7000
- SoundPoint IP VVX 1500
- SoundPoint IP 5000

Snom

Snom Models [300, 320, 360, 370]

- 300
- 320
- 360
- 370

Snom Models [710, 720, 760]

- 710
- 720
- 760

Snom Models [870]

- 870
- 820
- 821

Cisco/Linksys

Cisco SIP 79x0 Models [7940, 7960]

- 7940
- 7960

Cisco SIP 79x1G Models [7940G, 7941G, 7961G]

- 7940G
- 7941G
- 7961G

Cisco SIP ATA-18x Models [186, 188]

- ATA186
- ATA188

Linksys/Cisco/Sipura SPA Adapter Models [AG310, PAP2T, RTP300, SPA1001, SPA2102, SPA3102, SPA8000, WRP400, WRTP54G, WRT54G2]

- SPA2102
- SPA3102
- AG310
- PAP2T
- RTP300
- SPA1001
- SPA8000
- WRP400
- WRTP54G
- WRT54G2
- SPA112

Linksys/Cisco/Sipura SPA Phone Models 5xx, 3xx [303, 501G, 502G, 504G, 525G, 525G2]

- SPA501G
- SPA502G
- SPA504G
- SPA508G
- SPA509G
- SPA525G
- SPA525G2

- SPA303
- SPA512G
- SPA514G
- SPA301

Linksys/Cisco/Sipura SPA Phone Models [901, 921, 922, 941, 942, 962]

- SPA901
- SPA921
- SPA922
- SPA941
- SPA942
- SPA962

Yealink/Dreamwaver

Yealink/Dreamwave T1X Models: [T18]

- T18

Yealink/Dreamwave T2X Models: [T20, T22, T26, T28]

- T20
- T22
- T26
- T28

Yealink/Dreamwave T3X Models: [T32, T38]

- T32
- T38

Mitel

Mitel 5xxx Models: [5304, 5312, 5320, 5324, 5330, 5340, 5360]

- 5304
- 5312
- 5320
- 5324
- 5330
- 5340
- 5360

Contact us today to learn more.

Hardware Phone Support | 2 of 2